

OFFICE OF THE SUB DIVISIONAL OFFICER, P.W.D.

MAIHAR, SATNA (DT), M.P.

BUILDING FITNESS CERTIFICATE

(To be filled by the Inspecting Officer)


1. Name of the Officer :R. S. Twarri.....
2. Name of the school : **SANTHOME HR. SEC. SCHOOL**
3. Location with name of Education District Sub District : **Tehsil - Maihar, Distt. Satna , M.P., Pin- 485 771**
4. Classification of Building as specified in column 4 of the application for fitness certificate and size : **2674 Sq.Mtr.(Ground floor) & 2674 Sq. Mtr.(First floor)**
- Total area : 5349 Sq. Mts.**
5. Period for which the certificate is issued : **2020- 2021 (Two Years)**
6. Nature of defects, if any :
- (a). Foundation and basement : Not Applicable
- (b). Superstructure : Not Applicable
- (c). Doors and windows : Not Applicable
- (d). Wood works wrought and put up : Not Applicable
- (e). Roof : Not Applicable
- (f). Flooring : Not Applicable
- (g). Miscellaneous (cracks etc.) : Not Applicable
7. Any major defects noticed which will render the building unsafe in any manner : **No**
8. Whether maintenance works have been done properly : **Yes**
9. Whether the structure is sound or not for conducting classes : **Building is sound and safe**

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind , exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the school building was inspected by me on 10/1/2020 and found to be fit to conduct classes for the period of 2020-2021(Two years) for the reasons stated above.

Place : Maihar


SUB DIVISIONAL OFFICER

उप सभागा - मैहर

Date: 10/1/20

Entd . No- 386 / TS / 2020

Copy forwarded to : Principal , Santhome Hr. Sec. school

Maihar, Satna , M.P.